

Sunte House – Window Schedule (photographic record and brief description based on visual check from the interior)

First Floor (1F)	
South Elevation (S)	West (W)
	1F – SW1 (1) (Bedroom) - Timber-framed sash - Single-glazed (8 over 8) - Single pane crittal casement insert with metal fasteners - Modern Brass Brighton fastener Some (limited) cracking (mainly around the glazing bars and panes) and peeling of paint. Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.
	1F – SW1 (2)



1F – SW1 (3)



1F – SW2 (1) (Bedroom)

- Timber-framed sash
- Single-glazed (8 over 8)
- Modern Brass Brighton fastener

Some (limited) cracking (mainly around the glazing bars and panes) and peeling of paint. Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – SW2 (2) (Bedroom)



1F – SW2 (3) (Bedroom)

South Elevation (S)	Middle (M)
	1F – SM1 (1) (Bathroom) - Timber-framed sash - Single-glazed (8 over 8) - Modern Brass Brighton fastener Some (limited) cracking (mainly around the glazing bars and panes) and peeling of paint. Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.
	1F – SM1 (2) (Bathroom)

	1F – SM1 (3) (Bathroom)
South Elevation (S) 	East (E) 1F – SE1 (1) (Master Bedroom) - Timber-framed sash - Single-glazed (8 over 8) - Modern Brass Brighton fastener Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – SE1 (2) (Master Bedroom)

East Elevation (E)	South (S)
	1F – ES1 (1) (Master Bedroom) - Timber-framed sash - Single-glazed (8 over 8) - Modern Brass Brighton fastener Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber doesn't look soft or rotten. Overall appears to be in fair condition including the sash cord.
	1F – ES1 (2) (Master Bedroom)



1F – ES2 (1) Master Bedroom

- Timber-framed sash
- Single-glazed (8 over 8)
- Modern Brass Brighton fastener

Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber doesn't look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – ES2 (2) Master Bedroom



1F – ES2 (3) Master Bedroom

East Elevation (E)	Middle (M)
	1F – EM1 (1) Stairs Landing - Timber-framed sash - Single-glazed (8 over 8) - Single pane crittal casement insert with metal fasteners - Modern Brass Brighton fastener Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.
East Elevation (E)	North (N)
	1F – EN1 (1) Bedroom - Timber-framed sash - Single-glazed (8 over 8) - Single pane crittal casement insert with metal fasteners - Modern Brass Brighton fastener Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – EN1 (2) Bedroom



1F – EN2 (1) Bedroom

- Timber-framed sash
- Single-glazed (8 over 8)
- Modern Brass Brighton fastener

Some cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.

North Elevation (N)	Middle (M)
	1F – NM1 (1) (Study) - Timber-framed sash with simple curved horns - Single-glazed (8 over 8) - Modern Brass Brighton fastener Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.
	1F – NM1 (2) (Study)



1F – NM2 (Study)

- Timber-framed sash with simple curved horns
- Single-glazed (8 over 8)
- Modern Brass Brighton fastener

Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – NM3 (Study)

- Timber-framed sash with simple curved horns
- Single-glazed (8 over 8)
- Modern Brass Brighton fastener

Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – NM2 & 3 (Study)

North Elevation (N)

Northwest (NW)



1F – NNW1 (1) Hallway

- Timber-framed sash
- Single-glazed (8 over 8) (in the Georgian style)
- Modern Brass Brighton fastener

Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – NNW1 (2) Hallway

- Timber-framed sash
- Single-glazed (4 over 4)
- Brass Brighton fastener

Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – NNW2 (1) Bathroom

- Timber-framed casement (Twentieth Century based on physical evidence)
- Single-glazed (6 panes)
- Brass fasteners

Timber does not look soft or rotten. Overall appears to be in fair condition.

North Elevation (N)



West (W)

1F – NW1 (1) (Bedroom)

- Timber-framed sash (in the Georgian style)
- Single-glazed (10 over 10)
- Single pane crittal casement insert with metal fasteners
- Modern Brass Brighton fastener

Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.

	1F – NW1 (2) (Bedroom)
West Elevation (W) 	North (N) 1F – WN1 (1) Bedroom) - Timber-framed sash (in the Georgian style) - Single-glazed (10 over 10) - Single pane crittal casement insert with metal fasteners - Modern Brass Brighton fastener Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.

 A close-up photograph of a window frame and the adjacent brick wall. The window frame is white, and the brick is red. A white curtain is visible on the right side of the frame. The view through the window shows a clear blue sky and some trees.	1F – WN1 (2) Bedroom)
 A photograph showing a view through a window. The window frame is white, and the brick wall is visible on the right. The view outside shows a green lawn, trees, and a clear blue sky.	1F – WN1 (3) Bedroom)

West Elevation (W)



Middle (M)

1F – WM1 (1) (Ensuite Bathroom)

- Timber-framed sash (Twentieth Century based on physical evidence)
- Single-glazed (4 over 4)
- Modern Brass Brighton fastener

Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – WM2 (1) (Bathroom)

- Timber-framed sash (in the Georgian style)
- Single-glazed (10 over 10)
- Single pane critical casement insert with metal fasteners
- Modern Brass Brighton fastener

Some (limited) cracking of paint (mainly around the glazing bars and panes). Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.



1F – WM2 (2) (Bathroom)



1F – WM2 (3) (Bathroom)

West Elevation (W)

South (S)



1F – WS1 (1) (Hallway)

- Timber-framed sash
- Single-glazed (4 over 4)
- Modern Brass Brighton fastener

Some cracking of paint (mainly around and on the glazing bars and panes) and peeling of paint. Timber does not look soft or rotten. Overall appears to be in fair condition including the sash cord.

	1F – WS1 (2) (Hallway)
	1F – WS1 (3) (Hallway)