

Sunte House – Window Schedule (photographic record and brief description based on visual check from the interior)

Second Floor (2F)	
South Elevation (S)	West Side (W) Dormer (D)
	2F – SWD1 (1)
	- Timber-framed sash - Single-glazed (3 over 3) - Modern Brass Brighton fastener Some cracking and peeling of paint. Small gap between the sash bars and the bottom rail. Gap between the top rail and the head. Timber doesn't look soft or rotten. Overall appears to be in fair condition including the sash cord.



2F – SWD1 (2)



2F – SWD1 (3)



2F – SWD1 (4)

South Elevation



East Side (E) Dormer (D)

2F – SED1 (1)

- Timber-framed sash
- Single-glazed (3 over 3)
- Modern Brass Brighton fastener

Some cracking and peeling of paint. Small gap between the sash bars and the bottom rail. Small gap between the top rail and the head. Timber doesn't look soft or rotten. Overall appears to be in fair condition including the sash cord.



2F – SED1 (2)

East Elevation (E)



Dormer (D)

2F – ED1 (1)

- Timber-framed sash
- Single-glazed (3 over 3)
- Modern Brass Brighton fastener

Some cracking and peeling of paint. Gap between the top rail and the head. Timber doesn't look soft or rotten. Overall appears to be in fair condition including the sash cord.



2F – ED1 (2)



2F – ED1 (3)

North Roof Slope (NRS)	East Side (E)
	2F – NRSE1 - Timber-framed - Double-glazed (rectangular single pane) - Metal window lock Fair - Good condition.
North Roof Slope (NRS)	West Side (E)
	2F – NRSW1 - Timber-framed - Double-glazed (square single pane) - Metal window lock Some condensation in the glass indicating that the seal may have failed.

West Roof Slope (WRS)



2F – WRS1 (1)

- Timber-framed
- Double-glazed (rectangular single pane)
- Metal window lock

Fair - Good condition.



2F – WRS1 (2) (exterior view)

East Roof Slope (ERS)	North Side (N)
	2F – ERSN1 (1) - Timber-framed - Double-glazed (square single pane) - Metal window lock Some condensation in the glass indicating that the seal may have failed. Some cracking and peeling of paint.
East Roof Slope (ERS)	South Side (S)
	2F – ERSS1 (1) - Timber-framed - Double-glazed (square single pane) - Metal window lock Some condensation in the glass indicating that the seal may have failed.

East Roof Slope (ERS)



2F – ERS1 & 2 (exterior view) (2)