


Glazed conservatory panels overgrown by ivy.




**Observations upon
Proposed changes to
40 Hammerwood
Road (DM25/0605)
as they affect the
boundary with 38
Hammerwood Road**

Wall A shown as
retained.

Infill close boarded
panel B

Existing
conservatory wall C
(forming property
boundary) is shown
as demolished.
No boundary
replacement
detailed.



Existing Ground plan (Extract DrgTP03)

Proposed Site plan (Extract Drg C02)

