



GAP BETWEEN
EXISTING WALL &
BARN = 40MM

Existing rear wall is
severely damaged and in
poor condition. The
footings are unstable and
the wall is bowing.



Existing small section of wall is in poor condition and has detached from the wall of 63. It has been temporarily reattached to avoid further damage or injury.



EXISTING REAR LAYOUT

Exposed land/ bin
storage area
belonging to 63
visible in the rear
garden of 65/65a

