

The Castle, Hickstead

Window FF7 - *The cill has completely gone, 4" x 5/8" timber has been planted to outside face & top of cill in an attempt to conceal the rot. Pulley stile on left viewed from inside is completely rotten, again linings have been put over original linings to make them look good. The bottom rail is non-existent, the meeting rail on the top sash is rotten. Some of the glazing bars on the bottom sash have no moulding whatsoever. The top of the window is out of square by about 1 ½" on the left.*

