

Appendix C – Construction Photographs



Photo 1 - Pond earthworks



Photo 2 - Pond earthworks



Photo 3 - Pond earthworks



Photo 4 - Pond earthworks



Photo 5 - Pond lining



Photo 6 - Pond lining



Photo 7 - Pond lining



Photo 8 - Pond lining




Photo 9 – Completed pond




Photo 10 – Hydro-brake installed



WORK ALLOCATION SHEET

Customer	DHIS
Project/Address	13, 14 & Hill
Commencement Date	25.10.24
Work Description	Pond installation
Installed Pond to drawings Geo textile only installed in Bottom 245 membrane on top Back on a later date to do ^{Header} walls Header walls x2	
	
M2 Membrane Laid	2,205 m ²
M2 Excavator Soil	1,800 m ²
Top Soil	0

The above works have been carried out as per specifications and construction drawings and handed over to the contractors satisfactorily and hereby signed by both parties.

Subcontractor	Signature	
Header installation services	Print Name	
Water contractor	Signature	
	Print Name	

Comments/Remarks

GOOD JOB BY THE TEAM



Photo 11 – Hydro-brake pull handle



20 Mar 2025 08:23:52

Photo 12 – Manhole S44 Hydro-brake



Photo 13 – View of manhole S44 and outfall



Photo 14 – View of outfall



Photo 15 – Culvert A



Photo 16 – Culvert A membrane installation



Photo 17 – Culvert A membrane installation



Photo 18 – Culvert A membrane installation



Photo 19 – Culvert B



Photo 20 – Culvert B installation



Photo 21 – Culvert C installation



Photo 22 – Culvert C installation



Photo 23 – Culvert C installation



Photo 24 – Back drop to manhole S24



Photo 25 – Base of manhole S28



Photo 26 – Base of manhole S29



Photo 27 – Manhole S33



Photo 28 – Manhole S36