



WINDOW B1: 1/4 X 3/4 Single glazed unit
This is a bathroom window & gets very moldy & the paint peels off very year



WINDOW B1: This window was renovated in 2021 and this is a detail picture which shows the paint already peeling off, due to condensation on the single glazed window



WINDOWS E1 - E9: New single glazed centre bar sash windows. These are renovated almost yearly, but because they are such poor quality soft wood, the paint is constantly cracking and they need regular maintenance.

WINDOWS C1 - C3: Single glazed central bar sash windows with secondary glazing



These are the oldest windows are are mainly held together with filler. They have been renovated over the years, but it is not possible to repair them further. They are never opened as they are so fragile

Date: 29 October 2022	Title: Windows
Project & Version: Grove Cottage Windows	
Tel: 01273 831587 Mobile: 07769902676	
Email: info@elizabethbee.co.uk	
Address: 122 College Lane, Hurstpierpoint, West Sussex BN6 9AJ	

ELIZABETH BEE
creative interior design