



Plate 1: NE field, adjacent to entrance. Looking S towards entrance off B2118 road. WS29 flag in foreground.



Plate 2: NE field, adjacent to entrance. Looking SE towards adjacent residential property.



Plate 3: Looking SE along access road, towards entrance. Field adjacent to residential property to the left, eastern field to the right.



Plate 4: Looking NW along access road.



Plate 5: Looking W across eastern field.



Plate 6: Looking SW across eastern field.



Plate 7: Looking SE along treeline in the NE of the eastern field.



Plate 8: Looking E along access road from centre of site on the bend in the road.



Plate 9: Looking SW into eastern field. Basketball court site beyond metal fencing in the right of the photo.



Plate 10: Stockpile of chopped wood in NW corner of eastern field. Looking SW.



Plate 11: Looking E across eastern field.



Plate 12: Tree on boundary between eastern field and southern field.



Plate 13: Service cover and faint trace line across eastern field. Looking SW.



Plate 14: Service cover looking NW. Trace line visible and change in green metal fence line visible where service crosses fence boundary (visible at left of base of cone-shaped church building).



Plate 15: Fenceline between eastern and southern fields. Earthworks fill visible on right side of photo for level playing field.



Plate 16: Level playing field in southern field. Earthworks cut and fill visible.