



Plate 105: SE area of car park. Geogrid and gravel surface. Looking SE.



Plate 106: SE area of car park. Geogrid and gravel surface. Looking SE.



Plate 107: Area of field with some gravel, appeared to be reclaimed from car park. Drain visible in background. Looking E.



Plate 108: Access driveway from car park to access road. Looking SE.



Plate 109: Looking NW across car park.



Plate 110: Looking NE across field adjacent to car park. Earthworks bund in NW corner of field.



Plate 111: Looking N across field adjacent to car park. Earthworks bund in NW corner of field.



Plate 112: Looking N across NW portion of field adjacent to car park. Earthworks.



Plate 113: Looking NE from NW portion of field adjacent to car park. Earthworks.



Plate 114: Looking NW from NW portion of field adjacent to car park. Earthworks.



Plate 115: Looking E from NW portion of field adjacent to car park. Gas tank being installed.



Plate 116: Looking S towards gas tank being installed.



Plate 117: Looking SW. Gas tank being installed.



Plate 118: Looking S. Gas tank being installed. Gate to car park beyond.