

The Castle, Hickstead

Window FF9 - The cill is covered over with 3 ¼" x 5/8" timber on top and 2 ¾" x 5/8" on face only to improve appearance, it is completely rotten under. Pulley stiles have rot ¼" way up past pulley pocket. Top sash looks short & has been stuffed with paper to stop draughts. Outside lining is rotten but a piece of 4" x 1" has been nailed to face to make it look good. The bottom rail has badly decayed tenons that have come out of the stiles at the bottom.

