

APPENDIX B

Photographs



Photograph 17: Ridge beam missing in bay 5



Photograph 18: Rafter formed from multiple firring pieces



Photograph 19: Interface between Main Range roof and East Range roof



Photograph 20: Discontinued rafters in bay 1



Photograph 21: Gap between rafters and edge purlin



Photograph 1: NE corner of Bay 5



Photograph 2: NE corner of Bay 5



Photograph 3: Purlin to west elevation of Bay 5



Photograph 4: Fracture to purlin to west elevation of Bay 5



Photograph 5: West elevation of Bay 5 with added rafters over originals



Photograph 6: Wedges between earlier rafters and added rafters



Photograph 7: Dropped brace to be wedged back in place



Photograph 8: Modern rafters to east of Bay 2/3 (red) and purlin (green)



Photograph 9: Added frame above collars purlins to Bay 3 and 4



Photograph 10: Added frame above collars purlins to Bay 3 and 4



Photograph 11: Debris on ceiling backings



Photograph 12: Debris on ceiling backings



Photograph 13: Ceiling joist and spine beam jointing to Bay 5



Photograph 14: Ceiling joists in Bay 4



Photograph 15: Bay 1 roof structure



Photograph 16: Outer rafters to west elevation to Bay 1 and 2