

REF: DM/2

SITE VISIT REPORT SHEET

Date of Visit: 5/2/2026

Officer: Joseph Swift

THE SITE (Is block plan correct, levels, trees, highways/access, materials?)

Block plan correct, site slopes down from south to north
Access / Road access to both north and south of the field
Contains green field enclosures site, good brick fence to
north, west and east, with hedge to west.

ADJOINING LAND (Land use, adj. trees, boundary treatment, materials?)

N 1.2m c6 fence at back to main dwelling - one window to
site - has a 2m chain link to rear garden
S Existing track - with tree belt and open field beyond
E Wooded to bushes fields beyond.

W 1.5-2m hedge onto Road - Robin School, large tree
Nursery and debris at bottom of fence

STREET SCENE (What is the general character like? Would this be sympathetic?)

front on edge of dwelling area, contains sheep grass
- fence off road

OTHER COMMENTS (Main issues, Neighbour Notification correct, any action required?)

site robin on dogs