



View on front of main barn showing brickwork plinth and timber weatherboarding



View on lean-to structure to left end of main barn



View on brick barns adjoining main timber barn



View on barns from south west



View on southern end of southmost barn



View on rear of main barn at stagger



View on rear right corner of main barn from concrete barn showing stagger and brickwork wall of barn



View on underside of valley gutter and rear wall of brickwork barns



View on main barn gable end showing tie beam and gable framing



View on rear right corner showing weather damage and decay to corner post and sole plates.



View on front wall of main barn showing posts, tie beams, queen posts and purlins



View on front wall of brick barn showing walls and local damage to brickwork



Detailed view on front wall showing eroded bricks



View on barns showing roof trusses, purlins and rafters



View on gable wall between brick barns



View on roof structure of southernmost barn showing structure as adjoining barn



Detailed view on typical arear of front wall brickwork showing mortar recession



View inside of lean-to building to left of main barn