

	All patch repairs were carried out by mb membranes prior to our inspection.	
Signed: Adam McDermott (TGPV) Date: 28/03/2025		

Plot Overview Photographs



Marked up site plan.



A general overview of semi detached plots 8 & 9.



Overview of the Juta GP1 Gas Membrane that has been installed as an infill to plot 8.



Overview of the Juta GP1 Gas Membrane that has been installed as an infill to plot 9.



A general overview of plot 10.



Overview of the Juta GP1 Gas Membrane that has been installed as an infill to plot 10.



A general overview of detached plot 11.



Overview of the Juta GP1 Gas Membrane that has been installed as an infill to plot 11.



A general overview of semi detached plots 12 & 13.



Overview of the Juta GP1 Gas Membrane that has been installed as an infill to plot 12.