



A general overview of maisonette plots 6 & 7.



A general overview of semi detached plots 8 & 9.



A general overview of detached plot 10.



A general overview of detached plot 11.



A general overview of semi detached plots 12 & 13.



A general overview of maisonette plots 14 & 15.

Detailing Sample Photographs



Overview of the extended Juta GP1 gas membrane that has been hand welded to the previously installed gas membrane which now spans the perimeter cavity wall across plots 3-5.



Corner detailing to plot 3.



Weld defect found upon our inspection to plot 5.



Probe testing the repaired weld defect in plot 5.



Probe testing the hand welded membrane lap in plot 4.



Overview of the extended Juta GP1 gas membrane that has been hand welded to the previously installed gas membrane which now spans the perimeter cavity wall across plots 6 & 7.