



A general overview of detached plot 23.



Plot 23 infill installation overview.



Plot 23 infill installation overview.



A general overview of detached plot 24.



Plot 24 infill installation overview.



Plot 24 infill installation overview.



Plot 24 infill installation overview.

Detailing Sample Photographs



Evidence of the Juta GP1 SAM that has been used for the detailing on this project.



Plot 22 door threshold detailing.




Plot 22 hand welded membrane lap testing.



Plot 22 steel stanchion detail testing.



Plot 23 steel stanchion detail testing.



Plot 23 hand welded membrane lap testing.



Plot 23 pipe penetration detail testing.



Plot 24 pipe penetration detail testing.



Plot 24 pipe penetration detail testing.



Plot 24 hand welded membrane lap testing.



Plot 24 Juta GP1 SAM picture frame detail.