

REF: DM/ 24 / 2463 Highfields, HK

SITE VISIT REPORT SHEET

Date of Visit: 20.11.24

Officer: AT.

THE SITE (Is block plan correct, levels, trees, highways/access, materials?)

Land outside/^{what} appears to be inside garden boundary.
Hazel tree has been coppiced. Also another tree in
poor state - growing along ground - looks to be
outside ownership / inside WSCC highway boundary.
Level of kerb stones is lower on section of road adj.

ADJOINING LAND (Land use, adj. trees, boundary treatment, materials?)

N —

S —

E —

W —

STREET SCENE (What is the general character like? Would this be sympathetic?)

Will change street scene.

There is separate vehicular access with a garage.
Issue is whether WSCC concerns can be addressed.
Access would be close to road junction + would
open up front garden.

OTHER COMMENTS (Main issues, Neighbour Notification correct, any action

required?)

2 Highfields.