






Bin stores currently shown in frontages to be moved to back gardens across site.

12-29-2004

Project Name:

Project Number:

Project Location:

Project Date:

Project Description:

Project Objectives:

Project Scope:

Project Budget:

Project Manager:

Project Sponsor:

Project Stakeholders:

Project Risks:

Project Status:

Project Progress:

Project Issues:

Project Recommendations:

Project Summary:

Project Details:

Project Conclusion:


Project Appendix:


Project Summary:

Project Details:

Project Conclusion:

Project Appendix:



[illegible]

The services highlighted in blue will be excavated and reinstated by E&JH contractors, the excavation and reinstatement of the other items will be the responsibility of the customer.

	Program	Load
33KV Cable	Orange	Orange
44KV Cable	Orange	Orange
126KV Cable	Green	Green
20KV Cable	Green	Green
10KV Cable	Purple	Purple
4.16KV Cable	Purple	Purple
13V Water & 3ph Services	Blue	Blue
13V 3ph Services	Blue	Blue
Copper Earth Cable	Yellow	Yellow

[illegible]

To Disconnect: XXX Fender Flare



1

[illegible]

[illegible][illegible][illegible][illegible][illegible]

1

[illegible][illegible]

1

[illegible][illegible][illegible][illegible][illegible][illegible]

Plan Notes
This plan shows apparatus owned by the BUK Group. Any third party apparatus indicated on these drawings is shown for indicative purpose only. The information shown on this plan is given without warranty, the

accuracy cannot be guaranteed. No liability of any kind whatsoever is accepted by the company. Safe digging practices, in accordance with HSE/JMCT, must be used to avoid or minimise the risk of injury or damage to the property. This is the responsibility of the contractor. The company is a member of Ordnance Survey on behalf of HMSSD. © Crown copyright and database right 2004. All rights reserved. Ordnance Survey Licence number: 1100021563.

Developers Responsibility
If any apparatus have been used it becomes the responsibility of the developer to ensure it is safely protected, therefore backfilling should be carried out as soon as possible. The responsibility of the developer applies, including any damage caused will be fully redressed to the developer. It will be the developers responsibility to recover the costs from the third parties.


Revision Notes

		GTC, Winspit Business Park, Southall, W5 0 9JP Tel: 01856 246063 www.gtcs.co.uk
Last Edit By:		
Last Approved By: JACK MASON		

OS Ref:	535430.124266
Location:	Walstead Park, Scamps

Hill, Linstead, HAYWARDS HEATH, West Sussex, RH11 2QQ Developer/Client: Vistry Partnerships Ltd Drawing Number/Title: EN0002661-1.1 of 4 Entire site Rev'd
--

Network Number: N0023661		Project Number: N0023661-1	
Scale: 1:1000	Sheet Size: A0	Revision: 25-0	

[illegible]

The trenches highlighted in blue will be excavated and installed by DAK contractors. The expansion and reinstatement of the other trenches will be the responsibility of the customer.

	Perennial	Lat
230V Cable	Orange	Orange
660V Cable	Orange	Orange
120V Cable	Green	Green
208V Cable	Green	Green
480V Cable	Red	Red
600V Cable	Red	Red
0-3 Core Cable	Blue	Blue
Service Cable	Green	Green
Pilot Cable	Green	Green
Exposed Earth Cable	Yellow	Yellow

Live Cable
Cable Joint
Put End
Ducted Cable
Executed by BUK Contractors
Host Boundary
1 Way Link Box
4 Way Link Box
Earth
Unshielded Substation
Network Boundary

Additional
Is Disconnected



1

[illegible]

[illegible][illegible][illegible][illegible][illegible]

1

[illegible][illegible]

1

[illegible][illegible][illegible][illegible][illegible][illegible]

Plan Notes
This plan shows apparatus owned by the BUK Group. Any third party apparatus indicated on these drawings is shown for indicative purposes only. The information shown on this plan is given without warranty, the user assumes all liability for the use of the information.

Developers' Responsibility
These apparatuses have been sold to recipients under the responsibility of the developer. It is the developer's responsibility, therefore, that handling should be carried out as soon as possible. Recipients and repair of damaged apparatus, including administrative costs will be fully charged to the developer. It will be the developer's responsibility to recover the costs from the third parties.


Revision Notes


		GTC, Walspit Business Park, Southall, W5 0 9JP Tel: 01856 240063 www.gtec.co.uk
Last Edit By:		
I seek Approval By: VEDOV CELL INJAMAM		

OS Ref:	535430.124266
Location:	Walstead Park, Scamps

Hill, Lindfield, HAYWARDS
HEATH, West Sussex, RH16 1
Developer/Client:
Vistry Partnerships Ltd
Drawing Number/Title:
EN00023661.1.1 of 4 Entire site Rev 5

Network Number: N0023661		Project Number: N0023661-1	
Scale: 1:1000	Sheet Size: A0	Revision: 29-11	





Bin stores currently shown in frontages to be moved to back gardens across site