



- NOTES:
- 1) FIRE DETECTORS AND SOUNDERS ARE TO BE WIRED AND LINKED (CABLING NOT TO BE CHANNELED INTO FABRIC OF THE BUILDING, BUT CONNECTED TO LOCAL POWER SOURCES).
 - 2) REPLACEMENT WINDOW TO BE BE SIZED TO BE IDENTICAL TO EXISTING.
 - 3) REPLACEMENT WINDOW TO BE PAINTED WHITE AS PER EXISTING.
 - 4) REPLACEMENT WINDOW PROFILE TO BE AS CLOSE TO EXISTING AS POSSIBLE.
 - 5) FOR ADDITIONAL DETAIL OF PIPE RUNS AND MECHANICAL VENT, PLEASE REFER TO 56HS-001-P-31.



- EXISTING
- BOUNDARY
- PROPOSED
- FIRE SYSTEM

04	29-OCT-2024	FOR INFORMATION	JP	EB	EB
03	19-OCT-2023	FOR INFORMATION	JP	EB	EB
02	27-MAR-2023	FOR INFORMATION	JP	EB	EB
01	18-NOV-2022	FOR INFORMATION	JP	EB	EB
Rev	Date	Reason for Issue	Author	Checked	Approved
THE TOLL HOUSE					
PROPOSED - SECOND FLOOR LAYOUT					
JONATHON PEREZ & EMMA BURROWS THE TOLL HOUSE 56 HIGH STREET LINDFIELD SUSSEX RH16 2HL					
			T 07835 709 345 E jonathonperez@gmail.com		
DRAWING NUMBER	SHEET	SCALE	PAPER SIZE		
56HS-001	P-23	1:100 (@ A4)	A4		