


EXISTING GUTTER & PROPOSED SOLUTION



1. Propose to install new horizontal cast iron guttering to replace the existing cast iron guttering which runs across the front elevation of our house and the adjoining Clare House. This is due to the existing gutter being very corroded and currently acting as a water fall to the centre of the house between both properties.



MANOR HOUSE
LEWES ROAD
EAST GRINSTEAD
RH19 3SY