

Caroline Grist

From: [REDACTED]
Sent: 19 June 2026 11:15
To: Luke Holden
Subject: Fw: Soak report

Sent from Yahoo Mail for iPhone

Begin forwarded message:

[REDACTED]

Dear Luke,

We understand that a new borehole was drilled at the property for the purpose of soakage testing. Background information and video footage of the test have been provided by the site supervisor.

In summary, a road tanker was used to discharge approximately 8,800 litres of clean water into the borehole over a period of 314 seconds.

The observed inflow rate is consistent with discharge from a tanker operating at moderate engine speed through a rigid 4" diameter hose. We note that a standing head of water could not be established, and that the borehole did not overflow during the test. It is also understood that the borehole was supported using steel drill string casing.

On this basis, the test results indicate a minimum discharge (soakage) rate of approximately 28 litres per second.

Please let us know if you require any further clarification.

Kind regards

Elliot Toms CEnv BSc (Hons) MSc MEnvSci FGS
Managing Director



Head Office and Laboratory:

Unit 10, 19 Albert Drive, Burgess Hill, West Sussex,
RH15 9TN.

Tel: 0345 604 6494 / +44 (0) 1444 882 084

www.landscience.co.uk



This email and any attachment(s) is/are confidential and legally privileged. Unauthorised disclosure, copying or distribution is prohibited and may be unlawful. Any opinion or information contained herein may be personal to the sender and therefore not represent or be endorsed by Land Science Ltd. Whilst all reasonable care has been taken to avoid the transmission of viruses, no liability is accepted whatsoever. Registered Company: Land Science Ltd, Unit 10, 19 Albert Drive, Burgess Hill, RH15 9TN. Registered in England and Wales No. 7064804.

We love hearing feedback from our clients, good or bad, and you can do so [here](#).