

Date of Survey: 8/05/26

Site: 1 the Glades, East Grinstead

A site visit was undertaken to inspect x5 trees (Ref: **03E1, 03E2, 03E3, 03E4 & 03E5**) located on a verge between a public footpath and the above address.

Initial inspection showed none of the above trees to have any gross defects and the trees were in normal general health and condition on the day of inspection.

Low branches emanating from four of the five above trees were observed to be obstructing the adjacent footpath/pedestrian crossing.

Lateral limbs emanating from tree **03E5** were observed to be in contact with adjacent lamp columns.

Recommendations:

- **03E1, 03E2, 03E3, 03E4** - All branches obstructing adjacent footpath/pedestrian crossing to be cut back to the edge of pavement. Lift to 2.5m over the footpath.
- **03E5** - Cut back from adjacent lamp column to achieve minimum 1.5m clearance.