Site: Churchill Retirement Living

Location: Petlands Lodge, Church Rd, Haywards Heath RH16 3NY

Date: Tuesday 16th (19:00-00:00) & Wednesday 17th (00:00-07:00) July 2024

Time: 19:00-07:00 (12 Hrs)

Site: Churchill Retirement Living

Location: Petlands Lodge, Church Rd, Haywards Heath RH16 3NY

Date: Tuesday 16th (19:00-00:00) & Wednesday 17th (00:00-07:00) July 2024

Time: 19:00-07:00 (12 Hrs)

***Zero vehicles into / out of the vehicle access during the survey hours.**

Church Road / Churchill Retirement Living Vehicle Access (19:00-07:00) 15 minute intervals

	MOVEMENT 1									MOVEMENT 2									MOVEMENT 3									MOVEMENT 4								
	FROM CHURCH ROAD (EAST) RIGHT TURN INTO CHURCHILL RETIREMENT LIVING ACCESS									FROM CHURCHILL RETIREMENT LIVING ACCESS LEFT TURN OUT TO CHURCH ROAD (EAST)									FROM CHURCHILL RETIREMENT LIVING ACCESS RIGHT TURN OUT TO CHURCH ROAD (WEST)									FROM CHURCH ROAD (WEST) LEFT TURN INTO CHURCHILL RETIREMENT LIVING ACCESS								
	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL
1900-1915	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1915-1930	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1930-1945	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1945-2000	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2000-2015	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2015-2030	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2030-2045	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2045-2100	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2100-2115	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2115-2130	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2130-2145	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2145-2200	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2200-2215	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2215-2230	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2230-2245	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2245-2300	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2300-2315	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2315-2330	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2330-2345	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2345-0000	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0000-0015	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0015-0030	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0030-0045	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0045-0100	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0100-0115	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0115-0130	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0130-0145	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0145-0200	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0200-0215	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0215-0230	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0230-0245	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0245-0300	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0300-0315	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0315-0330	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0330-0345	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0345-0400	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0400-0415	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0415-0430	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0430-0445	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0445-0500	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0500-0515	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0515-0530	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0530-0545	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0545-0600	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0600-0615	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0615-0630	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0630-0645	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0645-0700	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1900-0700	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0.00**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0.00**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0.00**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0.00**

CHARGE SURVEYS

Site: Churchill Retirement Living

Location: Petlands Lodge, Church Rd, Haywards Heath RH16 3NY

Date: Tuesday 16th (19:00-00:00) & Wednesday 17th (00:00-07:00) July 2024

Time: 19:00-07:00 (12 Hrs)

***Zero vehicles into / out of the vehicle access during the survey hours.**

	MOVEMENT 1									MOVEMENT 2									MOVEMENT 3									MOVEMENT 4								
	FROM CHURCH ROAD (EAST) RIGHT TURN INTO CHURCHILL RETIREMENT LIVING ACCESS									FROM CHURCHILL RETIREMENT LIVING ACCESS LEFT TURN OUT TO CHURCH ROAD (EAST)									FROM CHURCHILL RETIREMENT LIVING ACCESS RIGHT TURN OUT TO CHURCH ROAD (WEST)									FROM CHURCH ROAD (WEST) LEFT TURN INTO CHURCHILL RETIREMENT LIVING ACCESS								
	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL	CAR	LGV	OGV1	OGV2	BUS	MCY	PCY	TOTAL	PCU TOTAL
1900-2000	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1915-2015	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1930-2030	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
1945-2045	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2000-2100	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2015-2115	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2030-2130	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2045-2145	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2100-2200	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2115-2215	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2130-2230	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2145-2245	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2200-2300	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2215-2315	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2230-2330	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2245-2345	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2300-0000	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2315-0015	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2330-0030	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
2345-0045	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0000-0100	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0015-0115	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0030-0130	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0045-0145	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0100-0200	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0115-0215	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0130-0230	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0145-0245	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0200-0300	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0215-0315	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0230-0330	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0245-0345	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0300-0400	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0315-0415	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0330-0430	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0345-0445	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0400-0500	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0415-0515	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0430-0530	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0445-0545	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0500-0600	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0515-0615	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0530-0630	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0545-0645	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
0600-0700	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00	0	0	0	0	0	0	0	0	0.00
	HOURLY TOTALS									HOURLY TOTALS									HOURLY TOTALS									HOURLY TOTALS								