

SITE VISIT REPORT SHEET

REF: DM/24/2976

DATE OF VISIT: 16/12/24

Devonshire House Haulcross

THE SITE:

Semi detached bldg - former offices.
2 storey painted brick with grey wooden windows. To rear extg metal stairs to ff
& large area of hardstanding with ss rear pitched roof ext.

ADJOINING LAND:

- N open boundary also access for no 1 & 2 ^{Lynwood} ^{cotts}
opp neigh lawbrce wall with high fence above
screening - approx 2.8m high? @ Lynwood
- S Hardstanding side elev of ss rear ext.
1.8m fence on boundary with neigh
- E Edg rear elev, stairs (Metal) access
- W side elev & 1.8m fence with neigh - beyond

STREETSCENE

Poss glimpses but seen in context of
habe & side boundary fencing @ Lynwood

OTHER COMMENTS

Staircase removed - g/f rear window enlarged
to patio & ff window & door to window only