



A273 Culvert Outfall to ditch on west side of A273 – May 2024



Ditch on west side of A273, at entrance of field culvert (ditch passes under timber fence into culvert entrance. Concrete bag work headwall just visible through fence)



A273 Culvert Outfall to ditch on west side of A273 – November 2022



Ditch to east side of electricity substation – during UKPN overhead cable undergrounding works – May 2024



Ditch to north side of A2300, near south west corner of St Pauls Catholic College – May 2024



A2300 Culvert entrance and headwall – May 2024



A2300 Culvert entrance – November 2022



A2300 Culvert entrance and upstream section of ditch part full with water beyond fence – November 2022



A2300 Culvert outfall – November 2022



A2300 Culvert entrance – November 2022

Site Walkover Images

Extract from WBLR Phase 1
Reserved Matters Application,
prepared by Campbell Reith



Image 1: Eastern end of land drainage ditch located to the north of sub station.



Image 2: Drainage ditch to the north of substation.
Waterlogged after prolonged heavy rainfall.

Project: Northern Arc WBLR, Burgess Hill
Project number: 13258
Client: Homes England

© CampbellReith 2019

CampbellReith
consulting engineers

LONDON 020 7340 1700 • MANCHESTER 0161 819 3060
REDHILL 01737 784 500 • BIRMINGHAM 0121 766 8009
BRISTOL 0117 916 1066 • www.campbellreith.com



Image 3: Northern end of land tributary to the Pook Bourne located to the west of sub station.



Image 4: Drainage ditch to the north of substation. Looking southwards into tributary of Pook Bourne