

Job

Job Reference	J-38667	Order Reference	INV-27718
Job Title	Camera Survey (Southern Water)		
Job Description	Conduct full camera survey from main sewer to property in order to create report whether a second property can be connected to the system.		
Entry Date	20/02/26 15:18	Required Completion Date	03/03/26 15:18
Completion Date	02/03/26 09:56		

Site

Site Name	Steve Dowds	Contact	stevedowds69@gmail.com
Address	48 Wickham Way, Haywards Heath, RH16 1UQ, RH16 1UQ		
Telephone	07894128505	Email	

Assignees

User	Job Start Time	Job Stop Time	Time
K - DRAINAGE ENGINEER Darren Lilley	02 Mar 2026 08:39	02 Mar 2026 09:56	1h 18m
Time on Job			1h 18m
Total Job Time			1h 18m

Notes

Note	By	Date
General: Arrived on site Made contact with homeowner of 48 He explained what he was required from me Camera line for manhole in grass verge outside property It goes along to next door number 46 Turns and goes into the main Line very good condition He got me to have a look at two road gullies on the other end of the street unable to do anything with them due to them holding water advised him that they require a Jetvac to empty, clean the gullies then jet lines to soak away	KD	02-Mar-2026 09:54

Job Images




Diagram
02 Mar 2026 09:54



Main manhole opposite camera head
02 Mar 2026 09:55



02 Mar 2026 09:55



Set up
02 Mar 2026 09:55



Manhole leaving 48
02 Mar 2026 09:55




Set up
02 Mar 2026 09:55

Operative Signature



Name: **K - DRAINAGE ENGINEER Darren Lilley**
By: **K - DRAINAGE ENGINEER Darren Lilley**
Date: **02/03/2026 09:56**

Customer Signature



Name:
By: **K - DRAINAGE ENGINEER Darren Lilley**
Date: **02/03/2026 09:56**