



Reinstate historic opening in wall. Wall currently in disrepair. Refer to following applications for information on proposed wall repair: DM/25/2644 and 2645. This will be an additional opening within the repaired wall. Pillar stonework design to match existing, using traditional techniques.

Historical photo and map below illustrates there was originally a pedestrian opening within this wall. Therefore this is being reinstated. The pillars will be replicated in style and material.



Existing stone balustrade elevation 1:100



Historic pedestrian opening




Historic Estate Plan 1925





Existing condition of wall

Existing Stone Balustade Standard Plan Detail 1:20 @A1





Existing Stone Balustade Standard Elevation Detail 1:25 @A1

Existing Stone Balustade Standard Section Detail 1:20 @A1




Historical image of wall.



Historic pedestrian opening and pillar





Proposed Stone Balustade - Standard Plan Detail 1:20 @A1



Proposed Stone Balustade - Standard Elevation Detail 1:25 @A1



Lower section of wall to be cut away to create new opening



Proposed Stone Balustade Standard Section Detail 1:20 @A1

23 Vine Street, Brighton BN1 4AG
e: studio@sticklandwright.co.uk
t: 01273 964051
Company registered in England No. 11222477

Disclaimer:
This drawing is the copyright of Stickland Wright Ltd. and may not be reproduced or used except by written permission. Figured dimensions to have precedence over scaling. Check all site dimensions prior to fabrication. Refer any discrepancies found to Stickland Wright.

Revisions:		Checked
/	17/03/2026	Issued for planning

Dwg No.	25041E-P-102 /
Drawing Title	New Opening in Balustrade
Address	Wykehurst House
Client	M Blencowe
Scale	1:100@A3
Stage	Planning
Drawn by	nc
Checked by	ns

STICKLAND WRIGHT
architecture + interiors
www.sticklandwright.co.uk