



Windows		
GW01	Living Room	Window frame in sound condition, no glazing bead
GW05	Dining Room	Good quality replacement
FW02	Bedroom 1	Window frame in sound condition, no glazing bead
FW03	Lobby	Window frame in sound condition, no glazing bead



notes + revisions				client + project		title		scale	number
				Telbridge Properties				1 : 50 @ A3	2236.S13
				Twineham Court Farmhouse				date	status
				Bob Lane, Twineham		Existing Side Elevation		14.11.2022	SURVEY