

REF: DM/ 25/0506 + 522 Grovelands fm, WH

SITE VISIT REPORT SHEET

Date of Visit: 6.3.25

Officer: AT.

THE SITE (Is block plan correct, levels, trees, highways/access, materials?)

Barn next to main house - in rural location
first floor is in residential use.

Hole for foundations has been dug, so work has commenced, although not above ground level.

ADJOINING LAND (Land use, adj. trees, boundary treatment, materials?)

N - adj drive / access

S - main house

E - access from road

W - parking at r/o b'g.

STREET SCENE (What is the general character like? Would this be sympathetic?)

Change in roof design - minor alt but issue with historical permission as amended plans formed part of description - ring agent.

OTHER COMMENTS (Main issues, Neighbour Notification correct, any action required?)

Site Notices erected on gate post.