

Project Title : WAYSIDE BALCOMBE						Project No.:	
TRIAL PIT RESULTS						Pit No. & Location	
Date : 10 - 07 - 2025 Engineer : M/K.E						BH1	
Ground Level							
Description	Legend	water Level	Depth	Reduced Level	Samples	Insitu Tests	Remarks
<i>Brown grey friable CLAY</i>			0m				<i>Ground level reduced by 0.45m</i>
<i>Grey CLAY, very stiff</i>			0.45		D		
<i>Dark brown CLAY IRONSTONE</i>		<i>Dry</i>	0.60				<i>N = 24 blows / 300mm</i>
<i>Dark brown stiff CLAY</i>			0.70		D	P	
			0.92				
			1m				
			2m				<i>Borehole 2 not drilled, clay too hard</i>
			3m				
			4m				
			5m				
KEY:- D Disturbed sample B Bulk sample W Water sample U U100 Undisturbed				INSITU TESTS :- Shear strength in K Pa P Penetrometer (PERTH) V Vane test			