

Plan showing onsite habitat existing on the date of application (28th March 2026)

Broken Fence



Disturbed ground of low ecological value, currently consisting of rough, recently cleared vegetation and bare ground

Grassland in Moderate/Good Condition

Plan showing onsite habitat following application approval and installation:

proposed development will introduce a narrow permeable sub-base to support a single-row solar array. The extent of this will be limited, with surrounding land retained and managed as grassland

Replaced Wooden Fence

