

## **APPENDIX B – SITE TOPOGRAPHICAL SURVEY**





## **APPENDIX C – SITE VISIT PHOTOGRAPHS AND ACCOMPANYING FIGURES**



**Legend**



-  Approximate Site Catchments
-  Natural Drainage Direction





**Legend**

- Photo Location Point



Catchment A

Photographs for Catchment A are presented in Table 3.1 below.

**Table 3.1: Catchment A Photographs**



**1.** View of watercourse to the northwest of the site looking west. Watercourse shown to take flows from north of site and direct them westward. Topography visibly sloping from east to west.



**2.** View of Catchment A looking north along western boundary. Standing water visible in west of site. Topography visibly sloping from east to west.



**3.** View of Catchment A in the northeast of the site looking west. Topography typically sloping from east to



**4.** Surface water flooding in the northeast corner of the site.

west although another low point is present in the northeast corner of the catchment.



**5.** Surface water flooding in the north of the site. Looking west. Flow observed to be east to west.



**6.** View of Catchment A looking northwest from the south of the catchment. Land shown to be sloping from southeast to northwest.

Catchment B

Photographs for Catchment B are presented in Table 3.2 below.