

REF: DM/22/033
SITE VISIT REPORT SHEET

Date of Visit: 16/3/2022

Officer: Caroline Grist

THE SITE (Is block plan correct, levels, trees, highways/access, materials?)

As per DM/29/06/03

ADJOINING LAND (Land use, adj. trees, boundary treatment, materials?)

N Brook Cottage - 2 side windows by garage

S

E

W

STREET SCENE (What is the general character like? Would this be sympathetic?)

OTHER COMMENTS (Main issues, Neighbour Notification correct, any action required?)

Tree info.