

TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY

Photos showing before and after

Existing Pier With cut slot & poor repair



Poor repair removed



Mortar repair to the cut slot & old repair

This was when mortar was wet



Photo taken when mortar dry

TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY

Sample mortar Biscuit showing colour against the stone



TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY



TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY



TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY

Sample cleaning to low level wall & balustrade before Thermatech cleaning



After cleaning



TRADITIONAL STONE

SPECIALISTS IN CONSERVATION | RESTORATION | STONEMASONRY

