

The Castle, Hickstead

Window FF8 - *The top sash & box are over 2" out of square, the cill is completely rotten, bottom rail of bottom sash has completely come away. Bottom of glazing bar tenons have completely gone, internal glazing bars completely missing. Outside linings to main box are rotten at bottom and the outside has been faced up with 4" x 3/4" to make it look good. Rotten and broken away or missing pulley stiles at cill trenching.*

