

SITE VISIT REPORT SHEET

Ref:	DM/25/1327
Site Address:	The Martlets Shopping Centre, Burgess Hill, West Sussex, RH15 9NN
Officer:	Steven King
Date of Visit:	06/06/2025

The Site (Is block plan correct, levels, trees, highways/access, materials?)	
Town centre site as per plans. Many retail units now empty. Part of site completely cleared. Office building boarded up	
Adjoining Land (Land use, adj. trees, boundary treatment, materials?)	
North:	Rear of units that front onto Church Walk. Ground floor residential properties on NW site that face towards site
South:	Surface car parking
East:	Existing retails buildings
West:	Sussex House office building and car parking, Police Station

--	--

Street Scene (What is the general character like? Would this be sympathetic?)

Town centre site, partially cleared of buildings. Existing buildings have common design

Other Comments (Main issues, Neighbour Notification correct, any action required?)

**Listed church to NW
See previous application**