

SITE VISIT REPORT SHEET

Ref:	DM/26/0207
Site Address:	Woodmans, Copthorne Common, Copthorne, Crawley
Officer:	Andrew Horrell
Date of Visit:	25.03.2026

The Site (Is block plan correct, levels, trees, highways/access, materials?)	
Dm/22/3539. Existing three black timber clad cabins with existing gravel access off driveway to Woodmans. Parking for 3+ cars on driveway.	
Adjoining Land (Land use, adj. trees, boundary treatment, materials?)	
North:	SEE DM/22/3539
South:	
East:	
West:	

Street Scene (What is the general character like? Would this be sympathetic?)

See 22/3539

Other Comments (Main issues, Neighbour Notification correct, any action required?)

Change to residential acceptable outside of BUA?