

SITE VISIT REPORT SHEET

Ref:	DM/26/0354
Site Address:	56 Oak Tree Drive, Hassocks, West Sussex, BN6 8YD
Officer:	Andrew Horrell
Date of Visit:	07.04.2025

The Site (Is block plan correct, levels, trees, highways/access, materials?)	
See DM/25/0147	
Adjoining Land (Land use, adj. trees, boundary treatment, materials?)	
North:	See DM/25/0147
South:	
East:	
West:	

Street Scene (What is the general character like? Would this be sympathetic?)

Front Dormers at No.20, 22, 24, No.55 (above garage) and No.69 (13/03531/FUL).

Other Comments (Main issues, Neighbour Notification correct, any action required?)

Parking for 1 car on driveway with garage.