

Gibbshaven Farm – East Grinstead

Schedule of Works – Barn and Granary



collapsed wall with roof removed



Scaffolding support frame prior to roof removal



New purlin supporting existing rafters and ready for existing outshot rafters to be installed



Rebuilt wall, with new sole, wall plates, and existing outshot rafters reinstalled