

Gibbshaven Farm – East Grinstead

Schedule of Works – Barn and Granary



Granary west elevation showing racking



Existing wall member fixed to new sole Plate. (No tenon remaining)



New concrete footings to support existing stone plinth



New oak wall members morticed into new sole plate. (Original members too rotten to replace), on reinstated stone plinth.