



1

2

3

4



5



6



7



8



9



10

Existing Garden Wall Images - Sections Requiring Repair

Refer to drawing 25041-P-200 for the existing plan showing the locations of sections of wall requiring repair

23 Vine Street, Brighton BN1 4AG
e: studio@sticklandwright.co.uk
t: 01273 964051
Company registered in England No. 11222477

Revisions:

/	16/10/202	Issued for planning
---	-----------	---------------------

Checked

▼

Dwg No. 25041C-P-201

Drawing Title Existing Garden Wall Photo Sheet
Address Wykehurst House
Client M Blencowe
Scale NTS @A1
Stage Planning
Drawn by nc
Checked by ns



architecture +
interiors
www.sticklandwright.co.uk