

SITE VISIT REPORT SHEET

REF: DM/26/

Unit A Conson Way.

THE SITE:

DATE OF VISIT: 13/4/26

Dev completed (constructed & peg laid out
Heras fencing surrounding steel
Built as per approval with 3 roller shutter
doors for 3 units

ADJOINING LAND:

- N Hardstanding (Parking area, grass verge
pavement & Commercial bldgs opp - frozen
foods
- S Fencing, parking area. further units
- E Parking (hardstanding access with neighbouring
commercial unit
- W Fencing, sub station, parking & highway

STREETSCENE

Industrial estate mix of commercial
uses surrounding

OTHER COMMENTS

Drainage and (oil not discharged)