


cut back a 2m clearance from building on row of Sycamore trees next to fire exit. Tree branches overhanging into the roof above warehouse side of the building along the boiler plant room



IMS Reference			
Issue Date	12/08/2025	Revision	1
Owner	Ground Control Trees Dept	Page	



IMS Reference			
Issue Date	12/08/2025	Revision	1
Owner	Ground Control Trees Dept	Page	