

Appendix C – Construction Photographs



Photo 1 - Pond earthworks



Photo 2 - Pond earthworks



Photo 3 - Pond earthworks



Photo 4 - Pond earthworks



Photo 5 - Pond lining



Photo 6 - Pond lining



Photo 7 - Pond lining



Photo 8 - Pond lining



Photo 9 – Completed pond



WORK ALLOCATION SHEET

Customer:	DHIS
Project/Address:	Burgess Hill
Commencement Date:	25.10.24
Work description:	Pond installation
Installed pond to drawings Geo textile only installed in Bottom 295 membrane on top Back on a later date to do Head Header walls x2 <i>[Signature]</i>	
M2 Membrane Laid	2,205m ²
M2 Geotextile laid	1,800m ²
Top Hats	6

The above works have been carried out as per specifications and construction drawings and handed over to the contractors satisfactorily and hereby signed by both parties.

Subcontractor -	Signature:	Date:
Keytec Installation services	Print Name: James Peters	<i>[Signature]</i>
Main contractor -	Signature:	Date: 25/10/24
	Print Name: Tony Pugh	

Comments/Remarks:
Great job by the team



Photo 10 – Hydro-brake installed



Photo 11 – Hydro-brake pull handle



20 Mar 2025 08:23:52

Photo 12 – Manhole S44 Hydro-brake



Photo 13 – View of manhole S44 and outfall



Photo 14 – View of outfall



Photo 15 – Culvert A



Photo 16 – Culvert A membrane installation



Photo 17 – Culvert A membrane installation



Photo 18 – Culvert A membrane installation



Photo 19 – Culvert B



Photo 20 – Culvert B installation



Photo 21 – Culvert C installation



Photo 22 – Culvert C installation



Photo 23 – Culvert C installation



Photo 24 – Back drop to manhole S24



Photo 25 – Base of manhole S28



Photo 26 – Base of manhole S29



Photo 27 – Manhole S33



Photo 28 – Manhole S36