

Appendix C - photographic schedule



1 – Lemon Meadow, West elevation, kitchen extension



2 – Lemon Meadow, West elevation, kitchen extension



3 – Lemon Meadow, West elevation



4 – Lemon Meadow & Yew Tree Cottage, West elevation



5 – Lemon Meadow, East elevation



6 – Lemon Meadow & Yew Tree Cottage, East elevation



7 – Lemon Meadow & Yew Tree Cottage, East elevation



8 – Lemon Meadow, West elevation



9 – Lemon Meadow, West elevation



10 – Lemon Meadow and Yew Tree Cottage, East elevation



11 – Lemon Meadow, East elevation



12 – Lemon Meadow, West elevation kitchen extension



13 – Lemon Meadow, East elevation kitchen extension



14 – Lemon Meadow, South elevation kitchen extension



15 – Underside of Sahtas tile when removed, soaked with moisture



16 – Sahtas tiles, crumbling



17 – Sahtas tile, showing delamination



18 – Underside of Sahtas tile delaminating, upper surface intact