

SITE VISIT REPORT SHEET

REF: DM/25/2995.

DATE OF VISIT: 5/1/26.

THE SITE:

Part of Rear garden of Chelsea Cottage.
Banded with 'leylandii' with access of new
door currently under construction. Old lapidary
timber clad SS bldg - garage 1st flr for
Chelsea Cott.

ADJOINING LAND:

- N 'leylandii' trees, on other side access
road of new site under construction
brick pillars on access.
- S SS timber art building in Chelsea
Cott.
- E Fence, 'leylandii' onto new site - houses
under construction.
- W garden - fencing, other garden of Chelsea
Cott - UK - no fence rear windows

STREETSCENE

set back from main highway. Rearward
door

OTHER COMMENTS

Have option to buy land from Chelsea
Cott.

Impact on Chelsea Cott - over cross to