

Bolney Park Farm

March 21, 2022

No fencing
around piles,
screening and
crushing plant
on site



Bolney Park
Farm

May 30, 2022

Concrete
“lego” blocks
on site,
growing pile of
demolition
waste, crusher
plant gone



Bolney Park Farm

June 30, 2022

Concrete “lego” blocks replaced with fence, demolition waste pile growing still, crusher plant returned to site



Bolney Park
Farm

August 16, 2022

Crusher moved into an operating position and in use. Significant piles of demolition waste and stockpiled product. Two excavators and two front end loaders now on site.



Bolney Park Farm

October 12, 2022

Huge pile of demolition waste now crushed and screened and either moved from site or relocated to new stockpiles.

Crusher relocated.

Two excavators and a front-end loader on site and a contractor grab lorry on site.



Bolney Park Farm

February 4, 2023

Increased stockpiles of various material types. Crusher and screening plants relocated. Rubbish containers relocated. Two excavators and a front-end loader on site. Staff on site even on a Saturday. New fuel storage facilities?



Bolney Park Farm

February 26, 2023

Crusher and screening plants relocated again. Screening plant discharge conveyor position changed. Significant movement of both “treated” and unprocessed waste piles over the last three weeks.



Bolney Park Farm

July 9, 2023

Crusher relocated
again.

Significant movement
of both “treated” and
unprocessed waste
piles.



Bolney Park Farm

September 14, 2024

Mobile crusher and
two backhoe loaders
on site.

Remarkably the
screening plant and
the front end loaders
have been removed
from the site although
they were clearly
operating earlier this
week from the noise.

